





CEE 16 A


L1 L2 L3 N PE



2 x CEE 16 A



3 x Schuko



2 x Schuko